

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: October 20, 2000

Calendar Quarter: The third quarter of 2000

Safety Recall Quarterly Report from July 1, 2000 through September 30, 2000

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Mazda SAS Control Module

1. NHTSA Safety Recall Campaign Number: 00V-004

Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000

The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,595 units

Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 1,912 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	1,912
Total	1,912

5. Items Determined to be Unreachable

Total Number Exported (To be reported in the '01 1st quarter report)

Total Number Stolen: (To be reported in the '01 1st quarter report)

Total Number Scrapped: (To be reported in the '01 1st quarter report)

Total Number Unable to Notify: (To be reported in the '01 1st quarter report)

Total Number Otherwise Unreachable: (To be reported in the '01 1st quarter report)

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.8

Report Date: April 27, 2001 Calendar Quarter: The First quarter of 2001

Safety Recall Quarterly Report from January 1, 2001 through March 31, 2001

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number:

00V-004

Mazda Recall Campaign Code Number:

SSP 40

2. The date notification to purchasers began:

September 8, 2000

The date notification of purchasers was completed:

September 8, 2000

3. The Total Number of Items Involved:

19,595 units

Number of Items Returned from Inventory or Remedied Prior to Sale:

0 units

4. Total Number of Receiving Corrective Action:

5,293 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	5,293
Total	5,293

5. Items Determined to be Unreachable

0 units

Total Number Exported:

2 units

Total Number Stolen:

23 units

Total Number Scrapped:

1,130 units

Total Number Unable to Notify:

219 units

Total Number Otherwise Unreachable:

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: July 31, 2001

Calendar Quarter: The Second quarter of 2001

Safety Recall Quarterly Report from April 1, 2001 through June 30, 2001

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number: 00V-004
 Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000
 The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,595 units
 Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 6,113 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	6,113
Total	6,113

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 2 units

Total Number Scrapped: 712 units

Total Number Unable to Notify: 1,130 units

Total Number Otherwise Unreachable: 219 units

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: October 31, 2001

Calendar Quarter: The Third quarter of 2001

Safety Recall Quarterly Report from July 1, 2001 through September 30, 2001

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number: D0V-004
 Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000
 The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,595 units
 Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 6,580 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	6,580
Total	6,580

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 2 units

Total Number Scrapped: 753 units

Total Number Unable to Notify: 1,130 units

Total Number Otherwise Unreachable: 219 units

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: January 31, 2002 Calendar Quarter: The fourth quarter of 2001

Safety Recall Quarterly Report from October 1, 2001 through December 31, 2001

Manufacturer: Mazda Motor Corporation

Recall Subject: 1985 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number: 00V-004
 Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000
 The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,595 units
 Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 6,866 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	6,866
Total	6,866

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 2 units

Total Number Scrapped: 777 units

Total Number Unable to Notify: 1,130 units

Total Number Otherwise Unreachable: 219 units

Safety Recall Quarterly Report Information
Required per 49 CFR Part 673.8

Report Date: April 26, 2002

Calendar Quarter: The First quarter of 2002

Safety Recall Quarterly Report from January 1, 2002 through March 31, 2002

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number: 00V-004
 Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000
 The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,695 units
 Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 8,130 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	8,130
Total	8,130

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 2 units

Total Number Scrapped: 846 units

Total Number Unable to Notify: 1,130 units

Total Number Otherwise Unreachable: 219 units

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: July 31, 2002

Calendar Quarter: The Second quarter of 2002

Safety Recall Quarterly Report from April 1, 2002 through June 30, 2002

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number: 00V-004
 Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000
 The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,595 units
 Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 9,008 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	9,008
Total	9,008

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 2 units

Total Number Scrapped: 906 units

Total Number Unable to Notify: 1,130 units

Total Number Otherwise Unreachable: 218 units

Safety Recall Quarterly Report Information
Required per 49 CFR Part 573.6

Report Date: October 31, 2002 Calendar Quarter: The Third quarter of 2002

Safety Recall Quarterly Report from July 1, 2002 through September 30, 2002

Manufacturer: Mazda Motor Corporation

Recall Subject: 1995 Miata SAS Control Module

1. NHTSA Safety Recall Campaign Number: 00V-004
Mazda Recall Campaign Code Number: SSP 40

2. The date notification to purchasers began: September 8, 2000
The date notification of purchasers was completed: September 8, 2000

3. The Total Number of Items Involved: 19,595 units
Number of Items Returned from Inventory or Remedied Prior to Sale: 0 units

4. Total Number of Receiving Corrective Action: 9,445 units

Repair Procedure	Number
Inventory Return	0
Inspection Only	0
Repaired/Replaced	9,445
Total	9,445

5. Items Determined to be Unreachable

Total Number Exported: 0 units

Total Number Stolen: 2 units

Total Number Scrapped: 934 units

Total Number Unable to Notify: 1,130 units

Total Number Otherwise Unreachable: 219 units